United Independent School District Repair and Installation of Playground Shade Structures RFP 058-2011

SECTION I: FOUR POST STANDARD - PYRAMID

SECTION I: FOOR FOST STANDARD - FTRAMID									
Riyed Enterprises LLC DESCRIPTION	To 8' High	To 12' High	Complete Tarp Repair	Hardware & Install for replacement Tarp & Complete Repair					
4 post std 18' X 18' pyramid	\$3,958.00	\$4,504.00	\$807.00	\$1,140.00					
4 post std 20' X 20' pyramid	\$4,140.00	\$4,770.00	\$940.00	\$1,196.00					
4 post std 24' X 24' pyramid	\$5,187.00	\$6,480.00	\$985.00	\$1,569.00					
4 post std 27' X 27' pyramid	\$6,900.00	\$7,300.00	\$1,250.00	\$1,911.00					
4 post std 30' X 30' pyramid	\$7,470.00	\$7,750.00	\$1,350.00	\$2,150.00					
Shade' N Net DESCRIPTION	• To 8' High	To 12' High	Complete Tarp Repair	Hardware & Install for replacement Tarp & Complete Repair					
4 post std 18' X 18' pyramid	\$5,623.00	\$5,745.00	\$810.00	\$1,053.00					
4 post std 20' X 20' pyramid	\$6,164.00	\$6,315.00	\$1,000.00	\$1,300.00					
4 post std 24' X 24' pyramid	\$7,320.00	\$7,660.00	\$1,440.00	\$1,872.00					
4 post std 27' X 27' pyramid	\$8,050.00	\$8,260.00	\$1,822.00	\$2,369.00					
4 post std 30' X 30' pyramid	\$8,780.00	\$9,130.00	\$2,250.00	\$2,925.00					
TF Harper and Associates LP DESCRIPTION	To 8' High	To 12' High	Complete Tarp Repair	Hardware & Install for replacement Tarp & Complete Repair					
4 post std 18' X 18' pyramid	\$4,727.00	\$5,243.00		\$2,146.00					
4 post std 20' X 20' pyramid	\$5,156.00	\$5,671.00		\$2,411.00					
4 post std 24' X 24' pyramid	\$6,555.00	\$7,070.00	No Bid	\$2,981.00					
4 post std 27' X 27' pyramid	\$7,064.00	\$7,577.00		\$3,469.00					
4 post std 30' X 30' pyramid	\$8,166.00	\$8,723.00		\$4,008.00					

Riyed Enterprises LLC			Complete Tarp	Hardware & Install for	
DESCRIPTION	To 8' High	To 12' High	Repair	replacement Tarp & Complete Repair	
4 post std 14' x 24' hip	\$4,320.00	\$4,575.00	\$750.00	\$1,140.00	
4 post std 16' x 24' hip	\$4,455.00	\$4,675.00	\$790.00	\$1,175.00	
4 post std 16' x 26' hip	\$4,750.00	\$4,850.00	\$800.00	\$1,185.00	
4 post std 16' x 36' hip	\$5,904.00	\$6,100.00	\$875.00	\$1,350.00	
4 post std 18' x 28' hip	\$5,166.00	\$5,275.00	\$800.00	\$1,185.00	
4 post std 18' x 30' hip	\$5,250.00	\$5,350.00	\$875.00	\$1,300.00	
4 post std 18' x 36' hip	\$6,645.00	\$6,850.00	\$900.00	\$1,575.00	
Shade' N Net DESCRIPTION	To 8' High	To 12' High	Complete Tarp Repair	Hardware & Install for replacement Tarp & Complete Repair	
4 post std 14' x 24' hip	\$5,708.00	\$5,835.00	\$840.00	\$1,092.00	
4 post std 16' x 24' hip	\$6,050.00	\$6,195.00	\$960.00	\$1,248.00	
4 post std 16' x 26' hip	\$6,400.00	\$6,555.00	\$1,040.00	\$1,352.00	
4 post std 16' x 36' hip	\$7,520.00	\$7,740.00	\$1,440.00	\$1,872.00	
4 post std 18' x 28' hip	\$7,280.00	\$7,475.00	\$1,260.00	\$1,638.00	
4 post std 18' x 30' hip	\$7,600.00	\$7,800.00	\$1,350.00	\$1,755.00	
4 post std 18' x 36' hip	\$7,800.00	\$8,160.00	\$1,620.00	\$2,106.00	
TF Harper & Associates DESCRIPTION	To 8' High	To 12' High	Complete Tarp Repair	Hardware & Install for replacement Tarp & Complete Repair	
4 post std 14' x 24' hip	\$5,021.00	\$5,404.00		\$2,185.00	
4 post std 16' x 24' hip	\$5,191.00	\$5,543.00	1	\$2,323.00	
4 post std 16' x 26' hip	\$5,241.00	\$5,626.00	1	\$2,420.00	
4 post std 16' x 36' hip	\$5,671.00	\$6,055.00	No Bid	\$2,893.00	
4 post std 18' x 28' hip	\$5,474.00	\$5,858.00]	\$2,675.00	
4 post std 18' x 30' hip	\$5,563.00	\$5,946.00]	\$2,781.00	
4 post std 18' x 36' hip	\$5,965.00	\$6,348.00		\$3,099.00	

SECTION II: FOUR POST STANDARD - HIP

SECTION III: FO	UR or SIX POST S	UPER STRUCTU	RES - HIP or PY	RAMID			
Riyed Enterprises LLC					Hardware & Instal		
DESCRIPTION	To 8' High	To 12' High	To 15' High	Complete Tarp Repair	for replacement		
					Tarp & Complete		
All Four (4) Post Units Super Structure 30 X 40 hip	¢0,000,00	¢0.000.00	¢0.750.00	£1 100 00	¢2.050.00		
Super Structure 40 X 40 hip	\$8,980.00 \$12,290.00	\$9,300.00 \$12,600.00	\$9,750.00 \$13,100.00	\$1,100.00 \$1,600.00	\$2,050.00 \$3,000.00		
All Six (6) Post Units	\$12,290.00	\$12,000.00	φ13,100.00	\$1,000.00	\$3,000.00		
Super Structure 40 X 50 hip	\$18,950.00	\$19,575.00	\$19,950.00	\$2,400.00	\$5,250.00		
Super Structure 40 X 60 hip	\$21,200.00	\$21,575.00	\$22,100.00	\$2,600.00	\$5,900.00		
All Eight (8) Post Units	ψ21,200.00	ψ21,070.00	φ22,100.00	ψ2,000.00	ψ0,300.00		
Super Structure 50 X 50 hip	\$22,840.00	\$23,150.00	\$23,900.00	\$2,600.00	\$6,100.00		
Super Structure 50 X 60 hip	\$26,840.00	\$27,660.00	\$28,300.00	\$2,750.00	\$6,500.00		
Proposal for Minor Work & Additional Items							
Price per Linear Foot for Minor Tarp Repairs				\$15.00/ (\$	95.00 min)		
· · · ·	afety note covers der	corations etc.)			,		
Percentage above Cost for any additional items (safety pole covers, decorations, etc.)					10%		
Price per Man-Hour for any other related duty not specifically listed Response time for Service Calls from time of receiving phone call					\$55.00 24 Hours		
Response time for service Calls from time of received	ving phone call			24 1	10015		
Shade' N Net	T O (1)	T (0) (1)	-	Complete Tarp	Hardware & Insta		
DESCRIPTION	To 8' High	To 12' High	To 15' High	Repair	for replacement Tarp & Complete		
All Four (4) Post Units					•		
Super Structure 30 X 40 hip	\$10,940.00	\$11,470.00	\$11,860.00	\$2,520.00	\$3,420.00		
Super Structure 40 X 40 hip	\$15,780.00	\$16,070.00	\$16,700.00	\$3,360.00	\$4,560.00		
All Six (6) Post Units	* · • • • • • • • • • • • • • • • • • •	.	••••	<i>+•</i> ,••••••	• •,••••••		
Super Structure 40 X 50 hip	\$20,555.00	\$21,460,00	\$21,830.00	\$4,200.00	\$5,700.00		
Super Structure 40 X 60 hip	\$23,940.00	\$24,450.00	\$25,000.00	\$5,040.00	\$6,840.00		
All Eight (8) Post Units	\$20,0 IOI00	<i>421,100100</i>	\$20,000,000	<i>\$6,610100</i>	\$6,610100		
Super Structure 50 X 50 hip	\$24,720.00	\$25,200.00	\$23,950.00	\$5,330.00	\$7,125.00		
Super Structure 50 X 60 hip	\$28,490.00	\$29,000.00	\$29,960.00	\$6,300.00	\$8,550.00		
Proposal for Minor Work & Additional Items							
Price per Linear Foot for Minor Tarp Repairs				\$1	5.00		
	25%						
Percentage above Cost for any additional items (safety pole covers, decorations, etc.) Price per Man-Hour for any other related duty not specifically listed					\$80.00		
Response time for Service Calls from time of receiving phone call					48 Hours		
	*						
TF Harper & Associates	T O (1) ^{<i>i</i>}	To 12' High	To 15' High	Complete Tarp	Hardware & Insta		
DESCRIPTION	To 8' High			Repair	for replacement Tarp & Complete		
All Four (4) Post Units	1						
Super Structure 30 X 40 hip	\$10,080.00	\$10,474.00	\$11,066.00		\$5,057.00		
Super Structure 40 X 40 hip	\$16,138.00	\$16,827.00	\$18,066.00	-	\$8,197.00		
All Six (6) Post Units	φ10,100.00	φ10,027.00	φ10,000.00	No Bid	φ0,107.00		
Super Structure 40 X 50 hip	\$23,075.00	\$23,747.00	\$25,830.00		\$10,219.00		
Super Structure 40 X 60 hip	\$24.042.00	\$24,714.00	\$26.840.00		\$12,444.00		
	Ψ= 1,072.00	φ2 1,7 17.00	ψ=0,0+0.00		ψ12, 111 .00		
		1	I	4	\$13,068.00		
All Eight (8) Post Units	\$39 136 00	\$40 364 00	\$44 038 00				
	\$39,136.00 \$40,400.00	\$40,364.00 \$41,627.00	\$44,038.00 \$45,357.00	-	\$15,215.00		
All Eight (8) Post Units Super Structure 50 X 50 hip Super Structure 50 X 60 hip							
All Eight (8) Post Units Super Structure 50 X 50 hip Super Structure 50 X 60 hip Proposal for Minor Work & Additional Items				- _	\$15,215.00		
All Eight (8) Post Units Super Structure 50 X 50 hip Super Structure 50 X 60 hip Proposal for Minor Work & Additional Items Price per Linear Foot for Minor Tarp Repairs	\$40,400.00	\$41,627.00			\$15,215.00		
All Eight (8) Post Units Super Structure 50 X 50 hip Super Structure 50 X 60 hip	\$40,400.00	\$41,627.00		2	\$15,215.00		